



AERO ACCESSORIES, LLC SERVICE BULLETIN

SERVICE BULLETIN: SB-011

Effective Date: 11-20-24

SUBJECT: Possible Damaged O-Ring

APPLICABILITY: Tempest® Electronic Fluid Pump

Affected Part: Electronic Fluid Pump

Background: There has been a report from the field of a fluid leak in a Tempest® Electronic Fluid Pump. The area of the leakage was observed at the grommet and, or the end of the lead wire. See Figure 1.




Figure 1

ISSUED			REVISED			Aero Accessories, LLC 2208 Air Park Drive Burlington, NC U.S.A.	PAGE No.	REVISION
MO	DAY	YR	MO	DAY	YR		1 of 3	-A-
11	20	24	12	05	24			



AERO ACCESSORIES, LLC SERVICE BULLETIN

SERVICE BULLETIN: SB-011

Effective Date: 11-20-24

SUBJECT: Possible Damaged O-Ring

APPLICABILITY: Tempest® Electronic Fluid Pump

Affected Lot Numbers:

A76088	A76284	A76284-1	A76411	A78360	A80543	A80564	A80591	A81842
17RD-	15UR-	18LT-	1720-	17VV-	18LK-	1888-	1889-	1CBV-
1A62-	16NU-	198E-	197C-	1AF5-	193P-	198G-	1A63-	
1ABH-	17LK-	19KX-	19KY-	1AR6-	1A6L-	19PP-	1ABL-	
1ADJ-	198C-	19RM-	19NY-	1AVN-	1ABJ-	1ABK-	1AE1-	
1AEJ-	19KW-		19UE-	1B9B-	1ARA-	1ANN-	1AF2-	
1B26-	19UF-		1A4M-	1BAC-	1AWF-	1BF2-		
1CY7-	1B25-		1AB5-	1BKK-	1BCK-	1BFX-		
	1CDM-		1AWP-	1BKL-	1CBN-	1BGE-		
	1CRB-		1B83-	1BKM-	1CDN-	1BR3-		
	1EK3-		1BEG-	1BWX-		1D80-		
			1BEH-	1C1M-		1DMW-		
			1BEJ-	1C21-				
			1D49-	1C22-				
			1DWP-	1CRC-				
			1ECY-	1D7Y-				
				1DDK-				
				1DMP-				
				1DMU-				
				1DMV-				
				1DTJ-				
				1DTK-				
				1E5C-				
				1E5D-				
				1ER5-				

Lot Number
is located
on separate
label above
mounting
flange.



SERIAL
NUMBER
198G03
LOT CODE

ISSUED			REVISED			Aero Accessories, LLC 2208 Air Park Drive Burlington, NC U.S.A.	PAGE No.	REVISION
MO	DAY	YR	MO	DAY	YR		2 of 3	-A-
11	20	24	12	05	24			



AERO ACCESSORIES, LLC SERVICE BULLETIN

SERVICE BULLETIN: SB-011

Effective Date: 11-20-24

SUBJECT: Possible Damaged O-Ring

APPLICABILITY: Tempest® Electronic Fluid Pump

Compliance: When installing a Tempest® Electronic Fluid Pump, operate the pump with fluid. Verify that no fluid is leaking from the fitment points, the end of the lead wire, or around the grommet, See Figure 1. If there is evidence of a leak, do not use the pump, return the pump for an exchange.

Previously Installed Pumps: Tempest® Electronic Pumps that have previously been installed need to be reinspected for leaks within 10 flight hours or 45 days from the effective date of this service bulletin, whichever occurs first. The inspection must be done while the pump is operating and the fluid is present.

If there is evidence of a leak, do not use the pump, return the pump for an exchange.

Safety First: Aero Accessories, LLC is a customer service-oriented company committed to technical innovation in pursuit of aviation safety. While Aero Accessories, LLC has no authority to compel owners to act responsibly and take prudent action to ensure their own safety and the safety of others, Aero Accessories, LLC believes compliance with this Service Bulletin is important and will help insure better maintained and better performing products.

Revision 12/5/24: Revised to remove lot numbers that were not affected.

ISSUED			REVISED			Aero Accessories, LLC 2208 Air Park Drive Burlington, NC U.S.A.	PAGE No.	REVISION
MO	DAY	YR	MO	DAY	YR			
11	20	24	12	05	24		3 of 3	-A-