


McFarlane Aviation
MC464-029
AUXILIARY LATCH



**WHY CHOOSE OUR PIPER
AUXILIARY DOOR LATCH HANDLE?**

For Piper Aircraft

A direct replacement for P/N 36590-02, P/N 464-029,
& P/N 63039-000

Engineered with Improvements

- Made from stronger materials – not plastic!
- Ceramic coating for corrosion resistance
- Lasts longer than the OEM
- Available as white, or paint to match your aircraft!



Manufactured by:




Any Questions?

McFarlane Aviation

MC464-029

AUXILIARY LATCH



Part Number	Replaces OEM	Piper
MC464-029	36590-02 464-029 63039-000	PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-181, PA-28-201T, PA-28-235, PA-28-236, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28S-160, PA-28S-180, PA-32-260, PA-32-300, PA-32-301, PA-32-301FT, PA-32-301T, PA-32-301XTC, PA-32R-300, PA-32R-301, PA-32R-301T, PA-32RT-300, PA-32RT-300T, PA-34-200, PA-34-200T, PA-34-220T, PA-44-180, PA-44-180T

Manufactured by:  **McFarlane** Any Questions?

VICTOR SIERRA