

PARTS MANUFACTURER APPROVAL NO: PQ2056CE-D
 PRODUCTION APPROVAL LISTING - SUPPLEMENT NO. 21
 DATE: March 22, 1999

Great Lakes Aero Products
 915 Kearsley Park Blvd.
 Flint, Michigan 48503

<u>Part Name</u>	<u>Part Number</u>	<u>Approved Replacement For</u>	<u>FAA Approval Basis and Approved Design Data</u>	<u>Installation Eligibility: MAKE</u>	<u>Installation Eligibility: MODEL</u>
BEECHCRAFT PILOT SIDE WINDOW WITH VENT	W- 2048, W/T-2048, W/G-2048	35-410291-SA14; 35-410291-132, - 628; 35-410291-652; 96-420011-634; 002-430052-1, -11	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2048, Rev. F, dtd., 10/17/96 INST A-2, Rev. A, dtd., 2/18/99	Raytheon Aircraft Company (Beech)	E33, E33A, E33C, F33, F33A, F33C, G33, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, 36, A36, A36TC, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A, 95, B95, B95A, D95A, E95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T-42A), 95-C55, 95-C55A
BEECHCRAFT DOOR WINDOW	W- 2049, W/T-2049, W/G-2049	35-400320-10, -32	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2049, Rev. C, dtd., 10/6/98 INST A-2, Rev. A, dtd., 2/18/99	Raytheon Aircraft Company (Beech)	E33, E33A, E33C, F33, F33A, F33C, G33, (S/N CD-1 & on, CE-1 thru - 632 & CJ-1 & up) 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, (S/N D-1 thru D-9855 except D-9819), 35- 33, 35-A33, 35-B33, 35-C33, 35-C33A, 36, A36 (S/N E-1 thru E-830 except E-754), D55, D55A, E55, E55A, (S/N TC-1 thru - 1935 & TE-1 thru - 1069), 56TC, A56TC (S/N TG-1 & up), 58, 58A (S/N TH-1 thru - -732), 95, B95, B95A, D95A, E95, (S/N TD-2 thru 721), 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A

BEECHCRAFT DOOR WINDOW WITH VENT	W- 2221, W/T-2221, W/G-2221	35-400320-4, -10; 35-400320-32, -34	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2221, Rev. B, dtd., 2/18/99 INST A-2A, Revised, 10/5/96	Raytheon Aircraft Company (Beech)	E33, E33A, E33C, F33, F33A, F33C, G33 (S/N CD-1 & on, CE-1 thru - 632 & CJ-1 & up), 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, (S/N D-1 thru D-9855 except D-9819), 35- 33, 35-A33, 35-B33, 35-C33, 35-C33A, 36, A36, (S/N E-1 thru E-830 except E-754), D55, D55A, E55, E55A (TC-1 thru -1935 & TE-1 thru -1069), 56TC, A56TC, (S/N TG-1 & up), 58, 58A, (S/N TH-1 thru -732), 95, B95, B95A, D95A, E95, (S/N TD-2 thru 721), 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A
BEECHCRAFT DOOR WINDOW WITH VENT	W- 2222, W/T-2222, W/G-2222	35-400320-4, -10; 35-400320-32, -34	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2222, Rev. B, dtd., 2/18/99 INST A-2B, Revised, 10/5/96	Raytheon Aircraft Company (Beech)	E33, E33A, E33C, F33, F33A, F33C, G33, (S/N CD-1 & on, CE-1 thru -632 & CJ-1 & up) 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, (S/N D-1 thru D-9855 except D-9819), 35- 33, 35-A33, 35-B33, 35-C33, 35-C33A, 36, A36, (S/N E-1 thru E-830 except E- 754), D55, D55A, E55, E55A, (TC-1 thru - 1935 & TE-1 thru -1069), 56TC, A56TC, (S/N TG-1 & up), 58, 58A, (S/N TH-1 thru - 732), 95, B95, B95A, D95A, E95, (S/N TD-2 thru 721), 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A
BEECHCRAFT DOOR WINDOW WITH VENT	W- 2223, W/T-2223, W/G-2223	36-430044-3, -5	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2223, Rev. A, dtd., 1-22-98 INST A-2C, Rev. A, dtd., 11/22/98	Raytheon Aircraft Company (Beech)	F33A (S/N CE-633 & up), V35B (S/N D-9819, D-9856 & up), A36, A36TC (S/N E-754, E-831 & up, EA-1 & up), E55, E55A (S/N TE- 1070 & up), 58, 58A (S/N TH-733 & up), 95-B55, 95-B55A (S/N TC-1936 & up)

BEECHCRAFT DOOR WINDOW WITH VENT	W- 2224, W/T-2224, W/G-2224	36-430044-3, -5	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2224, Rev. B, dtd., 1/26/99 INST A-2D, Rev. A, dtd., 12/9/98	Raytheon Aircraft Company (Beech)	F33A (S/N CE-633 & up) V35B (S/N D- 9819, D-9856 & up), A36 (S/N E-754, E- 831 & up), A36TC (EA-1 & up), E55, E55A (S/N TE-1070 & up) 58, 58A (S/N TH-733 & up), 95- B55, 95-B55A (S/N TC-1936 & up)
BEECHCRAFT BARON DOOR WINDOW	W- 2236, W/T-2236, W/G-2236	36-430044-5	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2236, Rev. A, dtd., 1/23/99 INST A2E, Rev. A, dtd., 1/23/99	Raytheon Aircraft Company (Beech)	F33A (S/N CE-633 & up) V35B (S/N D- 9819, D-9856 & up), A36 (S/N E-754, E- 831 & up), A36TC (S/N EA-1 & up)
BEECHCRAFT PILOT WINDOW ASSEMBLY WITH VENT	W-2237, W/T-2237, W/G-2237	35-410291-SA14; 35-410291-132, - 628; 35-410291-652; 96-420011-634; 002-430052-1, -11	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2237, Rev. None, dtd. 10/17/96 INST A-2F, Rev. None, dtd, 10/17/96	Raytheon Aircraft Company (Beech)	E33, E33A, E33C, F33, F33A, F33C, G33, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, 36, A36, A36TC, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A, 95, B95, B95A, D95A, E95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T-42A), 95-C55, 95-C55A
BEECHCRAFT PILOT WINDOW ASSEMBLY WITH VENT	W-2238, W/T-2238, W/G-2238	35-410291-221; 002-430052-1	Great Lakes Aero Products, STC No. SA00690CH, Amended 2/18/99; GLAP Drawing No. W-2238, Rev. None, dtd., 10/17/96 INST B1, Retyped, 6/10/93	Raytheon Aircraft Company (Beech)	F33, F33A, F33C, G33, V35B, A36, A36TC (S/N E-185 & up, EA-1 & up), E55, E55A, A56TC, 58, 58A, 95-B55, 95-B55A (S/N TC- 1259 & TC-1299 & up)

BEEHCRAFT
PILOT SIDE
WINDOW WITH
VENT

W-2239, W/T-2239,
W/G-2239

35-410291-221;
002-430052-1, -11


Great Lakes Aero
Products,
STC No. SA00690CH,
Amended 2/18/99;
GLAP Drawing No.
W-2239, Rev. A, dtd.,
11-28-98

INST B1, Retyped,
6/10/93

Raytheon Aircraft
Company
(Beech)

F33, F33A, F33C,
G33, V35B, A36,
A36TC (S/N E-185
& up, EA-1 & up),
E55, E55A, A56TC,
58, 58A, 95-B55,
95-B55A (S/N TC-
1259 & TC-1299 &
up)

-----End of Listing-----



Matthew E. Tomsheck

Manager, Manufacturing
Inspection District Office