

PARTS MANUFACTURER APPROVAL NO: PQ2625CE
PRODUCTION APPROVAL LISTING - SUPPLEMENT NO. 3

DATE: April 12, 2002

South Seas Ventures, Inc.
317 Catrell Drive
Howell, Michigan 48843

<u>Part Name</u>	<u>Part Number</u>	<u>Approved Replacement For</u>	<u>FAA Approval Basis and Approved Design Data</u>	<u>Installation Eligibility: MAKE</u>	<u>Installation Eligibility: MODEL</u>
Stainless Steel Passenger Step	002-430076-23	Modification Part	South Seas Ventures, Inc. STC SA01152CH issued 5/22/01. South Seas Ventures, Inc. Dwg.: 15007A, Rev. 9, dtd 1/23/01	Raytheon Aircraft Co. (Beech)	F33, F33A, F33C, G33, 35-C33, 35-C33A, N35, P35, S35, 36, A36, A36TC, B36TC, E55, E55A, 58, 58A, 95-B55, 95-B55A
Replacement Door Pin Strike Plate	002-430000-73	Raytheon (Beech) P/N: 002-430000-33 002-430000-73	Test reports and computations per 14 CFR 21.303. South Seas Ventures, Inc. Dwg. No. 12214A, Rev. 5, dtd 6/28/01	Raytheon Aircraft Co. (Beech)	V35A, V35B, 36, A36, A36TC, B36TC, E55, E55A, 58, 58A, 95-B55, 95-B55A
Battery Vent Fairing	002-400001-33	Modification Part	South Seas Ventures, Inc. STC SA01151CH issued 8/3/00, Reissued 5/29/01. South Seas Ventures, Inc. Dwg.: 14789A, Rev. 7, dtd 5/17/01	Raytheon Aircraft Co. (Beech)	E55, E55A, 58, 58A, 95-B55, 95-B55A

-----End of Listing-----



Matthew E. Tomscheck
Manager, Manufacturing
Inspection District Office