

Aircraft Make	Aircraft Model	Engine Model	AeroForce Turbocharger Part #	AeroForce Wastegate Part #	AeroForce Controller Part #
Aermacchi SpA	S210	TIO-360-A1B	407790-0002	470856-0001	470884-0001
AeroMercantil	Gavilan G358	TIO-540-W2A	465680-0005	470954-0005	470884-0010 and 470866-0002
Aerostar Aircraft Corporation	PA-60-601	IO-540-P1A5 (SE6WE)	CF600532-0001 or CF600532-	CF250001-0004	CF250002-0005
Aerostar Aircraft Corporation	PA-60-601P (SA2664WE) (S/Ns: 0001 thru 0455) (SE60WE) (S/Ns: 0456 and up) (SE81WE)	TIO-540-S1A5	CF600574-0001 or CF600574-0002 or CF600575-0001	CF250001-0004	CF250002-0005
Aerostar Aircraft Corporation	PA-60-602P	IO-540-AA1A5	CF600726-0001 or CF600726-	CF250001-0004	CF250002-0005
Aerostar Aircraft Corporation	PA-60-700P	(L)TIO-540-U2A	CF600803-0001 or CF600803-	CF250001-0004	CF250002-0006
Alexander Aircraft LLC	17-31TC Turbo	IO-540-G1E5	CF600572-0000	na	na
Alexander Aircraft LLC	17-31ATC (auto control)	IO-540-K1E5	CF600572-0000	na	na
Bell Helicopter ScottsBell 47 Inc	47G3B A Eng. ('61-62)	TVO-435-A1A	404460-0002	470622-0000	470620-0000
Bell Helicopter ScottsBell 47 Inc	47G3B E Eng. ('61-62)	TVO-435-E1A	406610-0015	470622-0000	470620-0000
Bell Helicopter ScottsBell 47 Inc	47G3B1 B Eng. ('63-67)	TVO-435-	404460-0002	470622-0001	470620-0001
Bell Helicopter ScottsBell 47 Inc	47G3B1 D Eng. ('63-67)	TVO-435-	406610-0015	470818-0001	470620-0002
Bell Helicopter ScottsBell 47 Inc	47G3B2A ('72-73)	TVO-435-F1A	406610-0015	470818-0001	470620-0003
Bell Helicopter ScottsBell 47 Inc	47G3B2 ('68-71)	TVO-435-G1A	406610-0015	470818-0001	470620-0003
BN Group Ltd	BN-2, BN-2A, BN-2A-6, BN-2A-8, BN-2A-9,	O-540-E4C5 (SE40WE)	CF600572-0000	na	na
Cirrus Aircraft	TAT Cirrus SR22 (SA10588SC and SE10589SC)	IO-550-N (SA03962AT)	466304-0003	(L)470842-0004(R) 22-6150026	470688-0005
Cirrus Aircraft	SR22T	TSIO-550-K	466304-0003	481064-0007	481058-0013

Commander Aircraft Group	114TC	TIO-540-AG1A	466011-0002	470954-0005	470844-0004 or 470886-
Commander Aircraft Group	115TC	TIO-540-AG1A	466011-0002	470954-0005	470844-0004 or 470886-
Commander Aircraft Group	112TC(A)	TO-360-C1A6D	600700-0000	na	na
Found Aircraft Canada Inc	FBA-2C3T	TIO-540-AH1A	406610-0002	470954-0009	481058-0007
Fuji Heavy Industries Ltd	710	TIGO-541-D1B	407800-0003	470818-0005	470924-0002
Fuji Heavy Industries Ltd	700	TIO-540-R2AD	465680-0001	470954-0001	481008-0020
GA 8 Airvan Pty Ltd	GA8-TC	TIO-540-AH1A	406610-0002	470954-0009	481058-0007
Helio Aircraft LLC	H-295 (SA156SO)	GO-480-G1D6 (SE124SO)	CF600572-0000	na	na
Helio Aircraft LLC	H-395 (SA125SO)	GO-480-G1D6 (SE124SO)	CF600572-0000	na	na
Jiazhuang	HO300 Sea Gull	TIO-540-A2C	406610-0020	470818-0003	470912-0001
Korea Aerospace Industries	KC-100 Naraon	TSIOF-550-K	466304-0003	481064-0007	481058-0011
Lancair	IV & IVP	TSIO-550-E	466304-0003	481064-0002	481058-0004
Lancair	IV & IVP	TSIO-550-B	466304-0003	470908-0017	481058-0004
Maule Aerospace Technology Inc	M-4-220C, M-4-220S, M-4-220T	6A-350-C1	na	na	n
Maule Aerospace Technology Inc	M-5-201TC	TO-360-F1A6D	600700-0000	na	na
Mooney International Corporation	305 Rocket	TSIO-520-NB	407810-0001	470908-0012	470836-0018
Mooney International Corporation	M20M	TIO-540-AF1A	466011-0002	470954-0005	470884-0004 or 470886-
Mooney International Corporation	M20M	TIO-540-AF1B	466011-0002	470954-0005	470884-0004 or 470886-
Mooney International Corporation	M22 (67 - 70)	TIO-541-A1A	406110-0005	470872-0001	481008-0009
Mooney International Corporation	M20K Encore	TSIO-360-SB	466642-0001	470842-0007	481008-0034
Mooney International Corporation	M20TN	TSIO-550-G	466304-0003	481058-0009	481058-0009
Mooney International Corporation	M20E & M20F	IO-360-A1A (SE32WE)	CF600573-0000	na	na
Mooney International Corporation	M20J (SA3555WE)	IO-360-A1D6D, A3D6D	CF600573-0000	na	na

Mooney International Corporation	M20A thru M20D, M20G (SA1156WE)	O-360-A1A or, O-360-A1D (SE154SO)	CF600573-0000	na	na
Mooney International Corporation	M20K (79 - 81)	TSIO-360-GB	CF600573-0000	na	na
Mooney International Corporation	M20K (82 & UP)	TSIO-360-LB,MB	CF600573-0000	na	na
Piper Aircraft Inc	PA31-310	TIO-540-A1A/A2A	406610-0020	470818-0003	470654-0001
Piper Aircraft Inc	PA23-250	O-540-A1D5/A1B5 or IO-540-J4A5/C4B5	406330-0001 or 406610-0003	470656-0001	470688-0003 or 470688-0004
Piper Aircraft Inc	PA23-250	TIO-540-C1A	406610-0021	470818-0003	470884-0004
Piper Aircraft Inc	PA31-310	TIO-540-	406610-0020	470818-0003	470884-0004
Piper Aircraft Inc	PA31-310	TIO-540-A2C	406610-0020	470818-0003	470884-0004
Piper Aircraft Inc	PA31-325	(L)TIO-540-F2BD	406610-0020	470818-0010	470884-0004
Piper Aircraft Inc	PA31-350	(L)TIO-540-J2BD	409170-0001	470818-0003	470884-0010
Piper Aircraft Inc	PA31P	TIGO-541-E	407800-0003	470818-0005	481008-0010
Piper Aircraft Inc	PA31P-350	TIO-540-V2AD	465680-0005	470954-0005	481008-0025
Piper Aircraft Inc	PA46-350P	TIO-540-AE2A	466642-0005	470954-0007	481008-0033
Piper Aircraft Inc	PA44-180T	(L)TO-360-	465398-0002	na	481058-0004
Piper Aircraft Inc	PA46-310P	TSIO-520-BE	466304-0003	481064-0002	481058-0004
Piper Aircraft Inc	PA-46 Conversion	TSIO-550-C	466304-0003	481064-0002	481058-0004
Piper Aircraft Inc	PA32-301T	TIO-540-AH1A	466011-0002	470954-0009	481058-0007
Piper Aircraft Inc	PA-23 & PA-23-160 (SA1260WE) and PA-23-	O-360-A1A & A1D (SE154SO)	CF600576-0000	na	na
Piper Aircraft Inc	PA-24-250 (SA811WE)	IO-540-C4B5 & C4C5 (SE6WE)	CF600572-0000	na	na
Piper Aircraft Inc	PA-23-250 & PA-E23-250 (S/Ns 27-2505 and up) (SA840WE)	IO-540-C4B5 & C4C5 (SE6WE)	CF600572-0000	na	na

Piper Aircraft Inc	PA-34-200 (SA2937WE)	L/IO-360-C1E6 (SE32WE)	CF600577-0000 or CF600573-0000 or	na	na
Piper Aircraft Inc	PA-32-260 (SA1557WE)	O-540-E4B5 (SE40WE)	CF600572-0000	na	na
Piper Aircraft Inc	PA-24-400 (SA2359WE)	IO-720-A1A (SE51WE)	CF600573-0000 or CF600576-	na	na
Piper Aircraft Inc	PA-30 & PA-39 (SA787WE)	L/IO-320-B1A & C1A (SE14WE)	CF600573-0000	na	na
Piper Aircraft Inc	PA32R-301T or PA32-301T	TIO-540-S1AD	406610-0026	na	na
Piper Aircraft Inc	PA32R-301 or PA32RT-300T	TIO-540-S1AD TIO-540-S1AD	406610-0026	na	na
Piper Aircraft Inc	PA-34-200T	(L)TSIO-360-	466240-0001	na	na
Piper Aircraft Inc	PA-28 RT201T	TSIO-360-F or	CF600573-0000	na	na
Piper Aircraft Inc	PA28-201T	TSIO-360-F orFB	CF600573-0000	na	na
Piper Aircraft Inc	PA28R	TSIO-360-For FB	CF600573-0000	na	na
Piper Aircraft Inc	PA-34-200T	(L)TSIO-360-	CF600573-0000	na	na
Piper Aircraft Inc	PA34-220T	(L)TSIO-360-KB	466240-0001	na	na
Piper Aircraft Inc	PA-23 & PA-23-160 (SE4-1637)	O-320-A & B (SE4-1638)	CF600572-0000	na	na
Piper Aircraft Inc	PA-23-235 & PA-23-250 (SA539WE)	IO-540-C1B5 & C1C5 (SE6WE)	CF600572-0000	na	na
Piper Aircraft Inc	PA-34-220T	(L)TSIO-360-RB	466642-0002	470842-0008	unk
Revo Inc	250	TIO-540-AA1AD	406610-0032	470954-0005	470884-0004 or 470886-
Revo Inc	LA-4-200 (SA2990WE)	IO-360-A1B (SE32WE)	CF600573-0000	na	na
Revo Inc	LA-4 & LA-4A (SA2270WE)	O-360-A1A or, O-360-A1D (SE154SO)	CF600573-0000	na	na
Siam Hiller Holdings Inc	UH12L	TIVO-540-A2A	404830-0001	470656-0000	470654-0000

SOCATA	TB 21	TIO-540-AB1AD	406610-0031	470954-0005	470884-0004 or 470912-
Textron Aviation Inc	T320 A - C (62 - 65)	TSIO-470-B,C,D	404350-0001	470618-0000	470616-0000
Textron Aviation Inc	T320, -1, A - C	TSIO-470-B,C,D	406610-0018	470618-0000	470616-0000
Textron Aviation Inc	T206 D-E (69 - 76)	TSIO-520-C	406610-0005	470908-0011	470688-0001
Textron Aviation Inc	177RG (SE4082NM)	IO-360-A1B6, A1B6D	466642-0005	470842-0004	470688-0005
Textron Aviation Inc	T210 J-L (69 - 76)	TSIO-520-H	406610-0005	470908-0011	470688-0005
Textron Aviation Inc	T207 (70 - 76)	TSIO-520-G	406610-0005	470908-0011	470688-0005
Textron Aviation Inc	TAT Cessna A185E, A185F (SA00214DE and	IO-520-D	406610-0029	470908-0011	470688-0005
Textron Aviation Inc	T310 P-Q (Up To 75)	TSIO-520-B	406610-0025	(L)470780-0014(R)470780-0013	470688-0005 or 470822-0001
Textron Aviation Inc	401A/402A (69)	TSIO-520-E	406610-0025	(L)470780-0015(R)470780-0016	470688-0005 or 470822-0001
Textron Aviation Inc	T206 G (77 & UP)	TSIO-520-M	406610-0005	470908-0011	470688-
Textron Aviation Inc	T207 (77 & UP)	TSIO-520-M	406610-0005	470908-0011	470688-0007
Textron Aviation Inc	T210 M-N (77 - UP)	TSIO-520-R	406610-0005	470908-0011	470688-0007
Textron Aviation Inc	Vitae Cessna	IO-550-N	406610-0005	470908-0011	470688-0007
Textron Aviation Inc	C210L,M,N 1972 - 1984 (SA02918CH)	IO-550-P	406610-0005	470908-0011	470688-0007
Textron Aviation Inc	TN550 Cessna T210L,M,N 1972 - 1984 (SA02918CH)	IO-550-P	406610-0005	470908-0011	470688-0007
Textron Aviation Inc	P210 (78 - 81)	TSIO-520-P	465680-0004	470908-9020	470688-0008
Textron Aviation Inc	TN550 Cessna P210N, 1978 - 1984 (SA02918CH)	IO-550-P	465680-0004	470908-0020	470688-0008
Textron Aviation Inc	411/411A (65 - 68)	GTSIO-520-C	404360-0004	(L)470780-0013(R)470780-0014	470782-0003

Textron Aviation Inc	T206 A-C (66 - 68)	TSIO-520-C	406610-0005	470908-0011	470782-0003
Textron Aviation Inc	T210 F-H (66 - 68)	TSIO-520-C	406610-0005	470908-0011	470782-0003
Textron Aviation Inc	T320 D - F (66 - 68)	TSIO-520-B	406610-0025	(L)470780-0014(R)470780-0013	470782-0003 or 470822-0001
Textron Aviation Inc	401/402 (67 - 68)	TSIO-520-E	406610-0025	(L)470780-0015(R)470780-0016	470782-0003 or 470822-0001
Textron Aviation Inc	414 (70 - 75)	TSIO-520-J	407810-0001	(L)470908-0012(R)470908-	470836-0001
Textron Aviation Inc	340 (SA1881SW)	TSIO-520-J	407810-0001	(L)470908-0012(R)470908-	470836-0001
Textron Aviation Inc	421/421A (68 - 69) 421B (70 - 75)	GTSIO-520-D	406990-0004	(L)470830-0010(R)470830-0020	470836-0003
Textron Aviation Inc	421B (70 - 75)	GTSIO-520-H	408610-0001	(L)470830-0010(R)470830-0020	470836-0003
Textron Aviation Inc	421C (76 & UP)	GTSIO-520-L/N	465930-0003	481064-0001	470836-0003
Textron Aviation Inc	340A (76 & UP)	TSIO-520-N/NB	407810-0001	(L)470908-0012(R)470908-	470836-0018
Textron Aviation Inc	414 (76 - 77)	TSIO-520-N/NB	407810-0001	(L)470908-0012(R)470908-	470836-0018
Textron Aviation Inc	RAM 340, 340A, 414, 414A Series II, III, IV, VI	TSIO-520-NB	407810-0003 or 407810-0004	(L)470908-0012(R)470908-	470836-0018
Textron Aviation Inc	RAM 340, 340A, 414, 414A Series V, VII	TSIO-520-NB	466412-0004 or 466412-0005	(L)470908-0012(R)470908-	470836-0018
Textron Aviation Inc	RAM 414A, Series V, VII	TSIOL-520-A	466412-0004 or 466412-0005	(L)470908-0012(R)470908-	470836-0018

Textron Aviation Inc	T310P - R (SA4011SW)	TSIO-520-NB	407810-0003 or 407810-0004	(L)470908-0012 (R)470908-	470836-0018
Textron Aviation Inc	T320D - F (SA4011SW)	TSIO-520-NB	407810-0003 or 407810-0004	(L)470908-0012 (R)470908-	470836-0018
Textron Aviation Inc	404 (77 & UP)	GTSIO-520-M	465930-0002	470908-0015	470836-0019
Textron Aviation Inc	414 (SA3682WE)	TSIO-520-N	407810-0001	(L)470908-0012 (R)470908-	470836-0020
Textron Aviation Inc	414A (78 & UP)	TSIO-520-N/NB	407810-0001	(L)470908-0012 (R)470908-	470836-0020
Textron Aviation Inc	402C (79 & UP)	TSIO-520-VB	406610-0028	470908-0013	470836-0021
Textron Aviation Inc	T337 (67 - 71)	TSIO-360-A	406970-0001	(F)470842- 0003(R)470842- 0004	470838-0001 or 481012-0
Textron Aviation Inc	T337 (67)	TSIO-360-B	406970-0001	(F)470842- 0003(R)470842- 0004	470838-0001 or 481012-0001
Textron Aviation Inc	340 (73 - 75)	TSIO-520-K	407810-0001	470908-0006	470934-0001
Textron Aviation Inc	T310 R (75 & UP)	TSIO-520-B	406610-0025	(L)470780- 0014(R)470780- 0013	470948-0001
Textron Aviation Inc	401B/402B (70 - 78)	TSIO-520-E	406610-0025	(L)470780- 0015(R)470780- 0016	470948-0001
Textron Aviation Inc	335	TSIO-520-E	406610-0025	(L)470780- 9015(R)470780- 9016	470948
Textron Aviation Inc	58P/58TC (76 - 78)	TSIO-520-L	409680-0011	470892-0002	481008-0002
Textron Aviation Inc	B60 (74 & UP)	TIO-541-E1C4	407540-0003	470818-0005	481008-0008
Textron Aviation Inc	A56TC	TIO-541-E1D4	407540-0003	470818-0005	481008-0008
Textron Aviation Inc	60/A60 (69 - 73)	TIO-541-E1A4	406110-0007	470864-0001	481008-0008

Textron Aviation Inc	A56TC	TIO-541-E1B4	406110-0007	470864-0001	481008-0008
Textron Aviation Inc	P337 (78 - 80)	TSIO-360-C	406610-0018 and 406610-0022	(F)470842- 0003(R)470842- 0004	481008-001
Textron Aviation Inc	T337 (73 - 77)	TSIO-360-C	406610-0018 and 406610-0022	(F)470842- 0003(R)470842- 0004	481008-0017
Textron Aviation Inc	58P/58TC (79 & UP)	TSIO-520-WB	409680-0001	470892-0002	481008-0022
Textron Aviation Inc	B60 (74 & UP)	TIO-541-G1AD	407540-0003	470818-0005	481008-0023
Textron Aviation Inc	V35-STC	TSIO-520-D	406610-0025	470818-0002	481012-0002
Textron Aviation Inc	T337 (78 - 80)	TSIO-360-H	465292-0001	(F)470842- 0003(R)470842- 0004	481012-0003
Textron Aviation Inc	T337	TSIO-360-JB	465292-0005	(F)470842- 0003(R)470842- 0004	481012-0005
Textron Aviation Inc	A, B36TC	TSIO-520-UB	406610-0029	470908-0017	481012-0006
Textron Aviation Inc	T303	(L)TSIO-520-AE	406610-0030	470954-0003	481058-0001
Textron Aviation Inc	P210 (82 & UP)	TSIO-520-AF	465680-0004	470908-9020	481058-0002
Textron Aviation Inc	LC41-550FG	TSIO-550-C	466304-0003	481064-0002	481058-0004
Textron Aviation Inc	T240	TSIO-550-C	466304-0003	481064-0002	481058
Textron Aviation Inc	T206	TIO-540-AJ1A	466881-0001	470954-9005	481058-0005
Textron Aviation Inc	T182T	TIO-540-AK1A	466642-0006	470954-0001	481058-0008
Textron Aviation Inc	310 C thru G (SA2383WE)	IO-470-D (SE96SO)	CF600572-0000	na	na
Textron Aviation Inc	95, B95, B95A, D95A, E95	IO-360-B1A, B1B	CF600576-0000	na	na
Textron Aviation Inc	95, B95, B95A, D95A, E95	O-360-A1A	CF600576-0000	na	na
Textron Aviation Inc	210, 210 A thru C, 210-5 (205), 210-5A (205A)	IO-470-E, IO-470- S (SE96SO)	CF600572-0000	na	na

Textron Aviation Inc	180, 180 A thru J (SA1157WE)	O-470-A, J, K, L, or R (SE25WE)	CF600572-0000	na	na
Textron Aviation Inc	182, 182 A thru P (SA1032WE)	O-470-L or O-470 R (SE25WE)	CF600572-0000	na	na
Textron Aviation Inc	N35, P35 (Rajay Parts LLC SA1252WE)	IO-470-N (SE96SO)	CF600572-0000	na	na
Textron Aviation Inc	H35, J35, K35, M35, 35-33, 35-A33, 35-B33, 35-C33, E33, F33 (SA1252WE)	O-470-G-C1, IO-470-C, IO-470-J, or IO470-K (SE25WE)	CF600572-0000	na	na
Textron Aviation Inc	35-C33A, E33A, E33C, S35, V35, V35A, V35B, F33A, F33C (SA2556WE)	TSIO-520-D (SE57WE)	CF600572-0000	na	na
Textron Aviation Inc	SMA Cessna 182Q,R (SA03302AT)	SR305-230-1	na	na	na
Textron Aviation Inc	T188C	TSIO-520-T	465292-0004	na	na
Textron Aviation Inc	T182	O-540-L3C5D	465292-0002	481044-0002	na
Textron Aviation Inc	TR182	O-540-L3C5D	465292-0002	481044-0002	na
Textron Aviation Inc	TAT Beecraft (SE5222NM)	IO-520-B, BA,BB or IO-550 - B	406610-0029	470908-0011	na
The Enstrom Helicopter Corp	F28C	HIO-360-E1AD	600700-0000	na	na
The Enstrom Helicopter Corp	F28F	HIO-360-E1BD or, F1AD	600700-0000	na	na
The Kings Engineering Fellowship	4500-300 4500-300 Series II (SA2657WE)	IO-540-K1B5 (SE6WE)	CF600572-0000	na	na
Triton Aerospace LLC	A500	TSIO-550-E	466304-0003	481064-0002	481058-0004
Twin Commander Aircraft LLC	685	GTSIO-520-F	408590-0002	470892-0001	481008-0004
Twin Commander Aircraft LLC	685	GTSIO-520-K	408590-0002	470892-0001	481008-0004
Twin Commander Aircraft LLC	500 A (SA683WE)	IO-470-M	CF600572-0000	na	na

Twin Commander Aircraft LLC	500 B (SA529WE)	IO-540-B1A5 (SE6WE)	CF600572-0000	na	na
Twin Commander Aircraft LLC	500 U (SA529WE)	IO-540-E1A5 (SE6WE)	CF600572-0000	na	na
Twin Commander Aircraft LLC	500 S (SA529WE)	IO-540-E1B5 (SE6WE)	CF600572-0000	na	na
Twin Commander Aircraft LLC	680 FP, L, FLP (SA2891WE)	IO-720 Mr. RPM Conversion	CF600573-0000 or CF600576-	na	na
Vulcan Air	P68-TC	TIO-360-C1A6D	CF60070-0000	na	na