

Int. Cl.: 7

Prior U.S. Cls.: 13, 19, 21, 23, 31, 34 and 35

Reg. No. 3,569,513

United States Patent and Trademark Office

Registered Feb. 3, 2009

**TRADEMARK
PRINCIPAL REGISTER**

TEMPEST

AERO ACCESSORIES, INC. (NORTH CAROLINA
CORPORATION)
1240 SPRINGWOOD AVENUE
GIBSONVILLE, NC 27249

FOR: AIRCRAFT ENGINE PARTS, NAMELY, AIR
PUMPS, FUEL PUMPS, CARBURETORS, CHECK
VALVE MANIFOLDS, VACUUM SWITCH MANI-
FOLDS, IGNITION SOURCES, IGNITION WIRES,
AIR FILTERS, AND OIL FILTERS, IN CLASS 7 (U.S.
CLS. 13, 19, 21, 23, 31, 34 AND 35).

FIRST USE 1-1-2001; IN COMMERCE 1-1-2001.

THE MARK CONSISTS OF STANDARD CHAR-
ACTERS WITHOUT CLAIM TO ANY PARTICULAR
FONT, STYLE, SIZE, OR COLOR.

SER. NO. 77-491,874, FILED 6-5-2008.

MARIA-VICTORIA SUAREZ, EXAMINING ATTOR-
NEY

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURING APPROVAL

Aero Accessories, Inc.
1240 Springwood Avenue
Gibsonville, N.C. 27249

PMA No. PQ1206CE
SUPPLEMENT NO. 97
DATED: April 22, 2009

| PART NAME | PART NUMBER | APPROVED REPLACEMENT FOR | APPROVAL BASIS & APPROVED DESIGN DATA | MAKE ELIGIBILITY | MODEL ELIGIBILITY |
|---------------------|-------------|---|---|---|--|
| Oil Filter, Spin On | AA48103-2 | Aero Accessories, Inc. P.N.AA48103, Champion Aerospace P.N. CH48103, CH48103-1 | Test and computations Per 14 CFR Part 21.303 (c)(4), Aero Accessories, Inc. DWG. Number AA48103-2, Rev. O Dated 04/17/09 or later FAA approved revision | Bombardier-Rotax, Franklin Engine Co., Teledyne Continental Motors (TCM), Textron Lycoming and Superior and any make where a 48103 series is installed. | Any type certificated Aircraft engine Where Aero Accessories, Inc. P.N. AA48103 or Champion P.N. CH48103 and CH48103-1 models where/are installed. |
| Oil Filter, Spin On | AA48108-2 | Aero Accessories, Inc. P.N.AA48108, Champion Aerospace P.N. CH48108, CH48108-1 | Test and computations Per 14 CFR Part 21.303 (c)(4), Aero Accessories, Inc. DWG. Number AA48108-2, Rev. O Dated 04/14/09 or later FAA approved revision | Bombardier-Rotax, Franklin Engine Co., Teledyne Continental Motors (TCM), Textron Lycoming and Superior and any make where a 48108 series is installed. | Any type certificated Aircraft engine Where Aero Accessories, Inc. P.N. AA48108 or Champion P.N. CH48108 and CH48108-1 models where/are installed. |
| Oil Filter, Spin On | AA48110-2 | Aero Accessories, Inc. P.N.AA48110, Champion Aerospace P.N. CH48110, CH48110-1 | Test and computations Per 14 CFR Part 21.303 (c)(4), Aero Accessories, Inc. DWG. Number AA48110-2, Rev. O Dated 04/17/09 or later FAA approved revision | Bombardier-Rotax, Franklin Engine Co., Teledyne Continental Motors (TCM), Textron Lycoming and Superior and any make where a 48110 series is installed. | Any type certificated Aircraft engine Where Aero Accessories, Inc. P.N. AA48110 or Champion P.N. CH48110 and CH48110-1 models where/are installed. |

----- END OF LISTING -----

Note:

- 1) Provide minor design changes in a manner as determined by the ACO. Handle major design changes to drawings and specifications in the same manner as that for an original FAA-PMA.
- 2) The FAA approved ICA for the above parts with their designs. These ICA may refer to those of the respective parts from the holders of type certificates. Otherwise, provide supplemental ICA for differences in the replacement parts. Make referral statements of supplemental ICA readily available per 14 CFR 21.50.


Melvin D. Taylor, Manager
Aircraft Certification Office


For Jim Reeves, Manager, Manufacturing
Inspection District Office